

Inspections Scheduled for 2/7/2023

Permit	Inspection Type	Inspector	Status	Estimated Start Time
214150	Final Building	James Edwards	Scheduled	12:30 PM
EH22-0621	OSSE Inspection	Carley Mayes	Scheduled	
201354	All Foundation	David VandenBos	Pass	
204214	Setbacks	David VandenBos	Pass	
212954	Final Building	James Edwards	Pass	
212995	Ground Plumbing	Jason Costa	Fail	
212995	Final Electric	Jason Costa	Fail	
212995	Ground Electrical	Jason Costa	Pass	
212995	Connect Electric	Jason Costa	Pass	
221085	Footings/Forms	David VandenBos	Pass	
221093	Connect Electric	James Edwards	Pass	
221093	Ground Plumbing	James Edwards	Pass	
221178	Final Electric	Cameron Wojciechowski	Pass	
221256	Pre-Gunite	James Edwards	Pass	
221495	Footings/Forms	Cameron Wojciechowski	Pass	
222108	Drywall	Cameron Wojciechowski	Pass	
222129	Underfloor Framing	David VandenBos	Pass	
222569	Underfloor Framing	Jason Costa	Rescheduled	
223347	Underfloor Framing	Cameron Wojciechowski	Pass	
223576	Final Building	James Edwards	Fail	
223898	Final Electric	Jason Costa	Pass	
223980	Final Electric	Cameron Wojciechowski	Pass	
224138	All Rough	Jason Costa	Pass	
224463	Final Building	Cameron Wojciechowski	Pass	
224464	Final Building	Jason Costa	Pass	
224495	Final Electric	David VandenBos	Pass	
224590	Final Electric	James Edwards	Rescheduled	

Permit	Inspection Type	Inspector	Status	Estimated Start Time
224599	Final Electric	Jason Costa	Pass	
224657	Final Electric	Ben Miller	Fail	
224657	Final Building	Ben Miller	Rescheduled	
224735	Final Electric	Cameron Wojciechowski	Pass	
230064	Footings/Forms	David VandenBos	Pass	
230110	Final Electric	David VandenBos	Pass	
230157	Final Building	James Edwards	Rescheduled	
230180	Final Mechanical	Cameron Wojciechowski	Pass	
230250	Ground Plumbing	James Edwards	Rescheduled	